


HPE ProLiant ML150 Gen9 Server



System components



Item	Description	Spare part number	<u>Customer self repair</u>
------	-------------	-------------------	-----------------------------

5	HPE 550 W power supply	766879-001	Optional ²
6	Hot-plug power input modules	754376-001	Mandatory ¹
	a) HPE 800 W/900 W Gold AC Power Input Module*	754376-001	Mandatory ¹
	b) HPE 900 W AC 240V DC Power Input Module*	830219-001	Mandatory ¹
7	RPS backplane assemblies	—	—
	a) HPE RPS backplane*	784636-001	Optional ²
	b) HPE 900 W AC 240VDC RPS Power Backplane*	830022-001	Optional ²
8	Front cable kit	792355-001	Optional ²
	a) Front panel USB	—	—
	b) Front panel LED	—	—
9	4 LFF hot-plug drive cage	792351-001	Optional ²
10	8 SFF hot-plug drive cage	792352-001	Optional ²
11	Heatsink	780977-001	Optional ²
12	System board (includes alcohol pad and thermal compound)	792346-001	Optional ²
13	Processors (include alcohol pad and thermal compound)	—	—
	Intel Xeon E5-2600 v3 processors		
	a) 1.60-GHz Intel Xeon E5-2603 v3, 6C, 85 W	762441-001	Optional ²
	b) 1.80-GHz Intel Xeon E5-2630L v3, 8C, 55 W*	762459-001	Optional ²
	c) 1.80-GHz Intel Xeon E5-2650L v3, 12C, 65 W*	762461-001	Optional ²
	d) 1.90-GHz Intel Xeon E5-2609 v3, 6C, 85 W*	762443-001	Optional ²
	e) 2.30-GHz Intel Xeon E5-2650 v3, 10C, 105 W*	762448-001	Optional ²
	f) 2.40-GHz Intel Xeon E5-2620 v3, 6C, 85 W*	762445-001	Optional ²
	g) 2.40-GHz Intel Xeon E5-2630 v3, 8C, 85 W*	762446-001	Optional ²
	h) 2.60-GHz Intel Xeon E5-2640 v3, 8C, 90 W*	762447-001	Optional ²
	i) 2.60-GHz Intel Xeon E5-2660 v3, 10C, 105 W*	762449-001	Optional ²
	Intel Xeon E5-2600 v4 processors		
	j) 1.70-GHz Intel Xeon E5-2650L v4, 14C, 65 W*	835609-001	Optional ²
	k) 1.70-GHz Intel Xeon E5-2603 v4, 6C, 85 W*	835599-001	Optional ²
	l) 1.70-GHz Intel Xeon E5-2609 v4, 8C, 85 W*	835600-001	Optional ²
	m) 1.80-GHz Intel Xeon E5-2630L v4, 10C, 55 W*	835608-001	Optional ²
	n) 2.00-GHz Intel Xeon E5-2660 v4, 14C, 105 W*	835605-001	Optional ²
	o) 2.10-GHz Intel Xeon E5-2620 v4, 8C, 85 W*	835601-001	Optional ²
	p) 2.20-GHz Intel Xeon E5-2630 v4, 10C, 85 W*	835602-001	Optional ²
	q) 2.20-GHz Intel Xeon E5-2650 v4, 12C, 105 W*	835604-001	Optional ²
	r) 2.40-GHz Intel Xeon E5-2640 v4, 10C, 90 W*	835603-001	Optional ²
14	DIMM	—	—
	DIMMs designed for Intel Xeon E5-2600 v3 processors		
	a) 4 GB, single-rank x8 PC4-2133R-15	774169-001	Optional ²
	b) 8 GB, single-rank x4 PC4-2133R-15*	774170-001	Optional ²
	c) 16GB, dual-rank x4 PC4-2133R-15*	774172-001	Optional ²
	d) 32 GB, dual-rank x4 PC4-2133R-15*	774175-001	Optional ²
	DIMMs designed for Intel Xeon E5-2600 v4 processors		
	e) 8 GB, single-rank x8 PC4-2400T-R*	819410-001	Optional ²
	f) 8 GB, single-rank x8 PC4-2400T-R STND*	852545-001	Optional ²
	g) 16 GB, single-rank x4 PC4-2400T-R*	819411-001	Optional ²
	h) 16 GB, dual-rank x4 PC4-2400T-R*	846740-001	Optional ²
	i) 32 GB, dual-rank x4 PC4-2400T-R*	819412-001	Optional ²
	j) 32 GB, dual-rank x4 PC4-2400T-L*	819414-001	Optional ²
15	Dedicated iLO port management module	792354-001	Optional ²
16	HPE 240 Host Bus Adapter*	779134-001	Optional ²
17	Mini-SAS cable kit*	792356-001	Optional ²
	a) 400 mm Mini-SAS cable	—	—

	b) 670 mm Mini-SAS H240 cable	—	—
	c) 670 mm Mini-SAS P440/ P840 Y-cable	—	—
	d) SATA to Mini-SAS cable	—	—
18	Power cable kit*	792357-001	Optional ²
	a) 465 mm hot-plug drive cage power cable	—	—
	b) 480 mm system board power cable	—	—
19	610 mm SATA cable*	465661-001	Optional ²

*Not shown

¹Mandatory—Parts for which customer self repair is mandatory. If you request Hewlett Packard Enterprise to replace these parts, you will be charged for the travel and labor costs of this service.

²Optional—Parts for which customer self repair is optional. These parts are also designed for customer self repair. If, however, you require that Hewlett Packard Enterprise replace them for you, there may or may not be additional charges, depending on the type of warranty service designated for your product.

³No—Some Hewlett Packard Enterprise parts are not designed for customer self repair. In order to satisfy the customer warranty, Hewlett Packard Enterprise requires that an authorized service provider replace the part. These parts are identified as "No" in the Illustrated Parts Catalog.